

L Number	Hits	Search Text	DB	Time stamp
10	5	(install\$5 adj3 (application program)) same erase same (old prior)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/22 12:27
11	11	(install\$5 adj3 (application program)) same (erase uninstall) same version	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/22 12:27
-	1209	update and install and firmware	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/02 16:33
-	288	(update and install and firmware) and (non-volatile adj memory)	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 10:21
-	123	((update and install and firmware) and (non-volatile adj memory)) and upgrade	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 10:22
-	1	"firmware upgrade patch"	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:11
-	26	modify same boot same image	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:31
-	162	modify same boot same memory	USPAT; US_PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:33
-	136	modify same boot same memory	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:34
-	184	update near2 bios	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:34
-	84	(update near2 bios) and network	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:55
-	416	update near2 firmware	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:55
-	159	(update near2 firmware) and network	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 13:55
-	61	((update near2 firmware) and network) and boot	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:46
-	62	"flash application"	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:52

	2	("5452454").PN.	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:54
	2	("5623604").PN.	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:55
	2	("5870610").PN.	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:55
	328	firmware near2 upgrade	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:57
	142	(firmware near2 upgrade) and "non-volatile"	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 16:57
	89	((firmware near2 upgrade) and "non-volatile") and boot	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 17:00
	59	((firmware near2 upgrade) and "non-volatile") and boot	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/06/30 17:00
	488	firmware near1 update	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 10:10
	422	(firmware near1 update) and memory	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 10:10
	258	((firmware near1 update) and memory) and ((local fixed) and storage)	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 10:11
	5	(((firmware near1 update) and memory) and ((local fixed) and storage)) and (boot near2 (image request))	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 10:11
	3	("5452454" "5623604" "5870610").PN.	USPAT	2003/07/01 10:17
	3	6266809.URPN.	USPAT	2003/07/01 10:26
	3535	(firmware BIOS operating\$1system) same (install\$5 (upgrade upgrading))	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:32
	3511	(firmware BIOS) same (install\$5 (upgrade upgrading))	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:32

	376	(firmware BIOS) same (install\$5 and (upgrade upgrading))	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:33
	173	(firmware BIOS) same (install\$5 and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:36
	20	(firmware BIOS) same ((install\$5 with application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:39
	0	(firmware BIOS) same ((install\$5 adj application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:39
	0	(firmware BIOS) same ((install adj application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:39
	1	(firmware BIOS) same ((install\$ adj application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:40
	205	((install\$ adj application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:40
	49	((install adj application) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 14:41
	363	((install adj application) installer) and (upgrade upgrading))	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:05
	37	"install application" and upgrade	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:07
	63	software with (installer "install application")	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:09
	393	firmware\$1 with (upgrade install patch)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:10
	789	firmware\$1 with (upgrade install\$5 patch\$2)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:10
	76460	(firmware\$1 with (upgrade install\$5 patch\$2)) or BIOS	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:10
	1446	(firmware\$1 BIOS) with (upgrade install\$5 patch\$2)	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:11
	53	((firmware\$1 BIOS) with (upgrade install\$5 patch\$2)) and installer	USPAT; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:38
	140	(717/178).CCLS.	USPAT; US-PPGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/07/01 15:39

-	11	(software adj patch\$2) with firmware	USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; EPO; JPO; DERWENT; IBM TDB	2003/07/07 16:44
-	11	(software adj patch\$2) with (firmware BIOS)	USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; EPO; JPO; DERWENT; IBM TDB	2003/07/07 16:44
-	14	(software adj patch\$2) same (firmware BIOS)	USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; EPO; JPO; DERWENT; IBM TDB	2003/07/07 16:44